MATERIAL SAFETY DATA SHEET								Approved su Búdget Ha. 45-20338	
	MANUFACTURER'S HAME AND FS	CM (Federal	Supply Code for	Manuleciwere,	)			HCY PHONE N	
	ADVANCED COATINGS & CHEMICALS							818-579-6270	
	ADDRESS (Number, Street, City, State, and ZIP Code)								
	4343 Temple City Blvd., Temple City, CA 91780  CHEMICAL NAME AND SYNONYMS  TRADE HAME AND SYN							ONYMS	
	ORGANIC SOLVENT		High Speed Drilling Fluid DPM 5172						
	CHEMICAL FAMILY	FORMULA							
	ORGANIC SOLVENT			(85)	30C-52 OY 30-C-109				
	FEDERAL STOCK NUMBER (FSN)	TO THIS PACKAGE	~.~cn3	the					
	MIL-STD-1341/NATIONAL FIRE PROTECTION ASSOCIATION STD 704M SIGNAL								
	FLAMMABILITY HEALTH REACTIVITY SPECIFIC HAZARD								
	PAINTS, PRESERVATIVES,	vo lume	THRESHOLD LIMIT VALUE (Unite)	ALLOYS	AND METALLIC COA	TINGS	7.	THRESHOL LIMIT VALI (Units)	
	PIGMENT	1,		BASE METAL PALL			6113		
	CATALY 1	多国		ALLOYS			704,		
	VEHICLE TO THE SE	10/		METALLIC COATINGS MAR			9/1		
	SOLVENTE	100		PILLER METAL PLUS COATING OR COME FLUX			10 Blee	<u></u>	
	AODITIVES			OTHERS		77	TAX TAX	¥	
	OTHERS					人事	1110	THRESHOL	
	HAZARDOUS MIXTURES OF OTHER LIQUIOS, SOLIDS, OR GASES By Total Volume of Solvents						volume	LIMIT VAL	
SECTION II - HAZARDOUS INGREDIENTS	CAS # Butyl Cellosolve (Ethylene Glycol Monombutyl Ether) 111-76-2						0.96	25 PPM	
	Deodorized Kerosene CAS # 8008-20-6						99.04	500 PPM	
SECTION III PHYSICAL DATA	BOILING POINT (PF.) Initial	33	80°F.	SPECIFIC GRAVITY (H20=1)			0.78		
	VAPOR PRESSURE (mm Hel)	Unavai		PRECENT V			100%		
֡֝֝֝֝֓֜֜֝֓֓֓֓֓֓֓֓֓֓֜֜֜֓֓֓֓֓֓֓֡֓֜֜֓֓֓֓֡֓֜֡֓֓֡֓֡֓֡֓֡֓֡֓֡֓֡֓֡֡֓	VAPOR DENSITY (AIR = 1)	Heavier		EVAPORATION RATE (Butyl Acetate = 1)			Slower		
	SOLUBILITY IN WATER	Negl	igible						
1	Water Clear with Distinct Solvent Odor.								
	FLASH POINT (Method used) 140°F. TCC			FLAMMABLE LIMITS	1.0% by Volume 7.0% by Volume				
2 2 2 2 2 2	EXTINGUISHING MEDIA FOAM, Dry Chemical, Carbon Dioxide SPECIAL FIRE FIGHTING PROCEDURES Full emergency equipment with self-contained breat								
EAFLUSION DALAND	apparatus should be worn by fire fighters.  UNUSUAL FIRE AND EXPLOSION HAZAROS  During a fire, irritating & toxic gases & smoke are present from decomposition. Is								
:   ני	from heat, sparks & open flame. Closed containers may burst when exposed to extrem								
ار ۲	FORM 1012 S/N 0102-02					P	LATE NO.	22473 (FRX	

	<del></del>									
SECTION V HEALTH HAZARD DATA	THRESHOLD LIMIT VALUE									
	As indicated. See attached sheet for results of animal inhalation tests of DiBasic Ester.									
	Eyes: Can cause severe irritation, redness, tearing and blurred vision. Skin: Prolonged or repeated									
	contact can cause irritation. Defatting to skin. Breathing: Excessive inhalation can cause masal									
	and respiratory irritation, dizziness and possible unconciousness. Swallowing: Can cause damage to throat EMERGENCY AND FIRST AID PROCEDURES									
	EMERGENCY AND	EMERGENCY AND FIRST AID PROCEDURES and esophagus.								
	On Skin: Thoroughly wash exposed area with soap & water. Remove contaminated clothing. Launder contaminate									
	clothing before reuse.									
	In Eyes: Flush with large amounts of water, lifting upper & lower lids occasional.									
	If Swallowed: Give two glasses of water. Induce vomitting. Call a physician. Never give anything by									
	month to an unconcious person. If Breathed: Remove individual to freash air. If breathing is difficult.									
	STABILITY	UNSTABLE		CONDITIONS T	O AVOID adm	inister oxygen,	If breathing has st	opped, give		
					art	ificial respirat	ion & call a doctor	immediately.		
								····		
1 4		STABLE	· · Χ·							
SECTION VI REACTIVITY DATA	INCOMPATABILIT				41.					
	Avoid metal hydroxides, such as sodium hydroxide; inorganic acids.									
	HAZARDOUS DECOMPOSITION PRODUCTS									
1 12 2	May form tox	c materials,	carbon	monoxide & ca	urbon dioxid	e, various hydro	carbons & acrid fume	es.		
l è		MAY OCCUR		CONDITIONS T	O AVOID		9. 3.			
I -	HAZARDOUS									
	POLYMERIZATION	MILL NOT								
		OCCUR	Х	None						
	STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED									
ES	Small Spills: Absorb liquid on paper, vermiculite or other absorbent material & transfer to hood.									
5										
CE.	Large Spills: Eliminate all ignition sources (flares, flames, including pilot lighting & eleotrical spark									
SPILL OR LEAK PROCEDURES	Persons not wearing protective equipment should be excluded from the area. Stop spill at source. Dit area									
		of spill to prevent spreadign pump into salvage tank. Remaining liquid may be taken up by sand, etc.shove								
EAC	1	WASTE DISPOSAL METHOD								
R L	Small Spills: Allow volatile portion to evaporate inhood. Allow sufficient time for vapors to clear hood									
٥٦	duck work. Destroy remaining material by burning in an iron pan.									
1	Large Spills: Destroy by liquid incineration. Material collected on absorbent material, may be deposited									
S	in a posted toxic substance landfill in accordance with local, state & federal regulations.									
	RESPIRATORY PROTECTION (Specify type) A Niosh/MSHA jointly approved self-contained breathing apparatus with									
,o					A jointly ap	oproved self-con	tained breathing app	paratus with		
¥.				and is advise	d. However,		roved respiratory ur	nder specified		
SECTION VIII - SPECIAL PROTECTION INFORMATIO	VENTILATION	LOCAL EXHAU					ions are also perm.			
	Face Velocty			exposure lev						
	>60 fpm in	MECHANICAL (			exposure.	OTHER				
	confirmed area	Recomme	ended							
5.5		Wear re	esistant	gloves	EYE PROTI			1		
EC	Such as buna,	such as buna, polivynyl chloride, etc. Chemical splash goggles in compliances w/Osha regulations								
S. S.	OTHER PROTECTIVE EQUIPMENT To prevent repeated or prolonged skin contact, wear impervious clothing									
	and boots. Eye bath and safety shower. PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING									
× 2	DO NOT Dreatne vapor. Use with adequate ventilation.									
물걸음	Do not get in eyes, on skin or on clothing. Accidental contact should be washed away immediately.									
107 107	Koon away from hoat and onon flamos. Koon assistance allowed									
SECTION IX SPECIAL PRECAUTIONS	Keep away from heat and open flames. Keep containers closed.  OTHER PRECAUTIONS  Since emptied containers retain product residues (vapors, liquid, and/or solid)									
" =		Strice en					s, liquid, and/or so	olid)		
×₹	all hazard precautions given in this data sheet must be observed.  PROPER SHIPPING (Article) NAME									
	Printing In						DOT CLASSIFICAT	ION		
SECTION X TRANS. DATA		OT MARKING	<u> </u>	-WEDGEN 1V			Combustible	1		
₹2		ONIARAM I				AUTIONS AND PRO		, 1		
¥. ₹	Red Avoid sparks or open flames. Avoid skin and eye contact.  DOT PLACARD PRECAUTIONS TO BE TAKEN IN TRANSPORTATION									
: <b>=</b>										
I	Combustible	j Avola ope	n Tlame	s and sparks.	кеер conta	iners closed.				

BOE-C6-0201831

int